

Draper City
Dry Weather Screening Checklist/SOP

Pre-inspection Items

- Map Outfall(s)
- Bring copies of reference material
 - This checklist/SOP (Document X-11)
 - Dry Weather Screening Flowchart (Document C-01)
 - Draper City Dry Weather Screening Report (Document X-12)
- Proper equipment
 - Clear sampling jar
 - Map showing location of outfall and connecting pipes, manholes, inlets
 - Visual monitoring report form (Document X-12)
 - Camera/Cell Phone

Inspection

- Check for dry weather discharge
- If discharge is present – pull sample
- Follow procedures on visual monitoring form
- Photo document findings
- If there is cause for concern move to inspection follow up procedures

Inspection Follow-Up Procedures

- File all Photos and documents
- Call health department and report findings 801-580-6681
- Trace discharge upstream by checking upstream manholes or inlets
- Find last manhole with any evidence of illicit discharge
- Look at surface improvements in the area to determine possible suspects
- If determination cannot be made from the surface investigations, then TV or smoke test line for unknown connections.